


Alkincoates Park - Walled Garden



KEY

- 1 New Metal Railings**
 Approximately 25m of Railings 1.8m high supported by around six or more uprights concreted into the surface of the platform. It may be worth considering adding a lockable gate for access for maintenance purposes. These railings would replace the heras fencing currently located in this position.
- 2 New Stock Fencing**
 Approximately 50m of post and wire fencing.
- 3 New Stock Fencing**
 Approximately 32m of post and wire fencing. Having a shorter fence would facilitate the possible relocation of one or more of the benches to the side of the path. (38m if extended to the lower hedge)
- 4 Existing Stock Fencing**
 This fencing has been in place for approximately 12 months and has been relatively successful in deterring ingress to the area behind the wall. Additional fencing could be installed to further deter ingress if needed.